CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Newton	1	Date:	12/20/2023	
Impoun	dment Name:	Primarry Ash	Pond	Time:	11:30 AM	
IEPA Number: W0780700001-01			01-01	Inspector(s):	Terry Hanratty	
Sky: Clear	Temp.:	45	Precip. (last 48 hrs):	0	Pool Elev.:	534.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM				DESCRIPTION		ļ	ACTION		
		YES	NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Cond	lition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Settlement			Х						
Erosion Rills	Erosion Rills		Х						
Animal Burrows			Х						
Misalignment			Х						
Vegetation (greater than 12")	-		Х	Blankensh	ip mowing this wee	ek of August 28th.			
UPSTREAM EMBANKMENT	General Cond	lition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging		Х		Minor sloghi	ng on south side-co	ontinuing to monitor	Х		
Seepage			Х						
Sink Holes			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Slope Protection / Rip Rap			Х						
Vegetation (greater than 12")			Х	Blankensh	ip mowing this wee	ek of August 28th.			
DOWNSTREAM EMBANKMENT	General Cond	lition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging			Х						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Vegetation (greater than 12")			Х	Blankensh	ip mowing this wee	ek of August 28th.			
SPILLWAY(S)	General Cond	lition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Х	R	emoved 1 stop log				
Obstructions Present			Х						
Seepage			Х						
Sand Boils (indicate if flowing and color)			Х						
Erosion Rills			Х						