CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	7/6/2021		
Impoundment Name:	Primarry Ash Pond	Time:	10:15 AM		
IEPA Number:	W0780700001-01	Inspector(s):	Kent Schafer		

Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

0.5"

Pool Elev.:

536

84

Temp.:

Sky: Partly Clou

ITEM		dition	for eac	ich section.				ACTIO	N
		YES	NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Settlement			Χ						
Erosion Rills			Χ						
Animal Burrows			Χ						
Misalignment			Χ						
Vegetation (greater than 12")			Χ						
UPSTREAM EMBANKMENT	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging		Χ		Minor slogh	ing on south side-c	ontinuing to monitor	Χ		
Seepage			Χ						
Sink Holes			Χ						
Animal Burrows			Χ						
Erosion Rills			Χ						
Slope Protection / Rip Rap			Χ						
Vegetation (greater than 12")			Χ						
DOWNSTREAM EMBANKMENT	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging			Χ						
Seepage			Χ						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Х						
Animal Burrows			Χ						
Erosion Rills			Х						
Vegetation (greater than 12")			Х						
SPILLWAY(S)	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Χ				1		
Obstructions Present			Χ				1		
Seepage			Х				1		
Sand Boils (indicate if flowing and color)			Х				1		<u> </u>
Erosion Rills			Х						