CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	11/3/2021	Date:		Newton	Station:		
	7:30 AM	Time:	ond	Primarry Ash Pond	ndment Name:	Impou	
	Terry Hanratty	Inspector(s):	1-01	W0780700001-01	IEPA Number:		
536	Pool Elev.:	0	Precip. (last 48 hrs):	34	Temp.:	Sky: Clear	

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

					DESCRIPTION			F	ACTIO	N
ITEM		YES	NO	MONITOR				INVESTIGATE	SENT TO DSM	
CREST	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			Χ							
Settlement			Χ							
Erosion Rills			Χ							
Animal Burrows			Χ							
Misalignment			Χ							
Vegetation (greater than 12")			Χ							
UPSTREAM EMBANKMENT	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			Χ							
Sloughing / Bulging		Χ		Minor sloghing	on south side-co	ontinuing to monitor	Χ			
Seepage			Χ							
Sink Holes			Χ							
Animal Burrows			Χ							
Erosion Rills			Χ							
Slope Protection / Rip Rap			Χ							
Vegetation (greater than 12")			Χ							
DOWNSTREAM EMBANKMENT	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			Χ							
Sloughing / Bulging			Χ							
Seepage			Χ							
Sink Holes			Χ							
Sand Boils (indicate if flowing	and color)		Χ							
Animal Burrows			Χ							
Erosion Rills			Χ							
Vegetation (greater than 12")			Χ							
SPILLWAY(S)	General Cond	ition:	Good	/ Fair / Poor	Repairs:	Date:				
Actively Flowing (provide de	pth)		Χ							
Obstructions Present			Χ							
Seepage			Χ							
Sand Boils (indicate if flowing	and color)		Χ							
Erosion Rills			Χ							