CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:		n: Nev	vton	_	Date:	11/17/2021	
Impoundment Name:		e: Primarry	Primarry Ash Pond		Time:	7:00 AM	
IEPA Number:		r: W07807	W0780700001-01		Inspector(s):	Terry Hanratty	
Sky:	Cloudy Temp	.: 59	Р	recip. (last 48 hrs):	0	Pool Elev.:	536

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					MONITOR	INVESTIGATE	SENT TO DSM
CREST General C	ondition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Settlement		Х					
Erosion Rills		Х					
Animal Burrows		Х					
Misalignment		Х					
Vegetation (greater than 12")		Х					
UPSTREAM EMBANKMENT General C	ondition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging			Minor sloghing on south side-continuing to mor	nitor X			
Seepage		Х					
Sink Holes		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Slope Protection / Rip Rap		Х					
Vegetation (greater than 12")		Х					
DOWNSTREAM EMBANKMENT General C	ondition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging		Х					
Seepage		Х					
Sink Holes		Х					
Sand Boils (indicate if flowing and color)		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Vegetation (greater than 12")		Х					
SPILLWAY(S) General C	ondition:	Good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		Х					
Obstructions Present		Х					
Seepage		Х					
Sand Boils (indicate if flowing and color)		Х					
Erosion Rills		Х					