## **CCR Impoundment Weekly Inspection** 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:		Newton	<u> </u>	Date:	11/24/2021	
	Impoundment Name	Primarry Ash	Pond	Time:	7:45 AM	
	IEPA Number	W078070000	01-01	Inspector(s):	Terry Hanratty	
Sky:	Cloudy <b>Temp.</b> :	45	Precip. (last 48 hrs):	0	Pool Elev.:	535.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Circle General Cond  ITEM		101 68	CH Section.		ACTION			
		ES NO DESCRIPTION		N	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General C	Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Χ						
Settlement		Х						
Erosion Rills		Х						
Animal Burrows		Х						
Misalignment		Х						
Vegetation (greater than 12")		Х						
UPSTREAM EMBANKMENT General C	Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Х						
Sloughing / Bulging			Minor slogh	loghing on south side-continuing to monitor		Χ		
Seepage		Х						
Sink Holes		Х						
Animal Burrows		Х						
Erosion Rills		Х						
Slope Protection / Rip Rap		Х						
Vegetation (greater than 12")		Х						
DOWNSTREAM EMBANKMENT General C	Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Х						
Sloughing / Bulging		Х						
Seepage		Х						
Sink Holes		Х						
Sand Boils (indicate if flowing and color)		Х						
Animal Burrows		Х						
Erosion Rills		Х						
Vegetation (greater than 12")		Χ						
SPILLWAY(S) General C	Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		Χ						
Obstructions Present		Χ						
Seepage		Х						
Sand Boils (indicate if flowing and color)		Χ						
Erosion Rills		Χ						