CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	6/23/2021
Impoundment Name:	Ash Pond	Time:	9:30
IEPA Number:	W1438050005-01	Inspector(s):	Rick Kelley

Sky: <u>Cloudy</u> Temp.: <u>774°F</u> Precip. (last 48 hrs): <u>0.02"</u> Pool Elev.: <u>447.5</u>

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						ACTION		
		NO	NO DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST General C	ondition	Good	Fair / Poor Repair	s: Date:				
Cracking		X						
Settlement		X						
Erosion Rills		X						
Animal Burrows		X						
Misalignment		X		7.				
Vegetation (greater than 12")		X						
UPSTREAM EMBANKMENT General Condition		Good	Fair / Poor Repair	s: Date:				
Cracking		X						
Sloughing / Bulging		X						
Seepage		Χ						
Sink Holes		X						
Animal Burrows		X						
Erosion Rills		X						
Slope Protection / Rip Rap		X						
Vegetation (greater than 12")		X						
DOWNSTREAM EMBANKMENT General C	ondition.	Good	Fair / Poor Repair	s: Date:				
Cracking		X		13.002.00				
Sloughing / Bulging		Υ						
Seepage		X						
Sink Holes		X						
Sand Boils (indicate if flowing and color)		×						
Animal Burrows		X						
Erosion Rills		χ						
Vegetation (greater than 12")		X						
SPILLWAY(S) General C	ondition	Good	Fair / Poor Repair	s: Date:				
Actively Flowing (provide depth)	X		x 2"					
Obstructions Present		X						
Seepage								
Sand Boils (indicate if flowing and color)		X X						
Erosion Rills		X						