## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	7/21/2021
Impoundment Name:	Ash Pond	Time:	3:30 p.m.
IEPA Number:	W1438050005-01	Inspector(s):	Rick Kelley

Sky: <u>OkrCast</u> Temp.: <u>87.4°F</u> Precip. (last 48 hrs):

additional sheets as necessary. Circle General Condition for each section.

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

ITEM						A	ACTION		
		NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM		
CREST	General Condition	Good	y Fair / Poor	Repairs:	Date:				
Cracking		V							
Settlement		V							
Erosion Rills		1							
Animal Burrows									
Misalignment		V							
Vegetation (greater than 12")									
UPSTREAM EMBANKMENT General Cond		600d	Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		1							
Seepage		V							
Sink Holes		V		+ T-1000+000 - 1000-000					
Animal Burrows		V							
Erosion Rills		V			V 1920				
Slope Protection / Rip Rap		1							
Vegetation (greater than 12")		/							
DOWNSTREAM EMBANKMENT	General Condition	Good	Fair / Poor	Repairs:	Date:				
Cracking									
Sloughing / Bulging		V							
Seepage									
Sink Holes						3.8			
Sand Boils (indicate if flowing and color)		V			120 1				
Animal Burrows									
Erosion Rills						516			
Vegetation (greater than 12")		V							
SPILLWAY(S)	General Condition	Bood	Fair / Poor	Repairs:	Date:				
Actively Flowing (provide dep	th)		$\alpha$ 1.	5"					
Obstructions Present		~							
Seepage		-							
Sand Boils (indicate if flowing and color)			/						
Erosion Rills									