CCR Impoundment Weekly Inspection

	35	LL. A	DM. Code 845 / 40	CFR Part 257				
Station:	Edwards			21				
Impoundment Name:	Ash Pond		•	M	£.			
IEPA Number:	W1438050005-0			Inspect	lley			
Sky: Rain Temp.:	75°F	. P	recip. (last 48 hrs):	0.3"	Pool	Elev.:	44	7.4
YES" responses require description at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "INVES	TIGAT	E", please indicate date					
ITEM							ACTIO	N
		NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		~						
Settlement								
Erosion Rills		V						
Animal Burrows		/						
Misalignment		1						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition	Good	Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage		/						
Sink Holes		/						
Animal Burrows		V						
Erosion Rills		V		·				
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")								
DOWNSTREAM EMBANKMENT	General Condition:	Bood	Fair / Poor	Repairs:	Date:			

Repairs:

£ 1.5"

Date:

V

/

General Condition Good/ Fair / Poor

Cracking

Seepage

Sink Holes

Animal Burrows

Erosion Rills

Seepage

Erosion Rills

Sloughing / Bulging

Sand Boils (indicate if flowing and color)

Vegetation (greater than 12")

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

SPILLWAY(S)

Obstructions Present