## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Edwards	Date:	9/1/2021
Impoundment Name:	Ash Pond	Time:	10:30 A.M.
IEPA Number:	W1438050005-01		Rick Kelley

Sky: Partly Temp.: 75°F Precip. (last 48 hrs): 0.38" Pool Elev.: 447.4

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM			DESCRIPTION		ACTION			
		NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condition	Good	Fair / Poor Repairs: Date:					
Cracking		-						
Settlement								
Erosion Rills				200 CO. 100 CO				
Animal Burrows								
Misalignment	ī							
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition	Good	Fair / Poor Repairs: Date:					
Cracking		<b>V</b>						
Sloughing / Bulging		/						
Seepage		1						
Sink Holes		1						
Animal Burrows		1						
Erosion Rills								
Slope Protection / Rip Rap		1						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT	General Condition	Good	Fair / Poor Repairs: Date:					
Cracking		-						
Sloughing / Bulging		/						
Seepage		V						
Sink Holes								
Sand Boils (indicate if flowing and color)		V						
Animal Burrows		/						
Erosion Rills		4						
Vegetation (greater than 12")								
SPILLWAY(S)	General Condition:	Good					1	
Actively Flowing (provide dep	oth) 🗶		× 2"					
Obstructions Present								
Seepage		1						
Sand Boils (indicate if flowing and color)								
Erosion Rills		V						