CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:

Erosion Rills

Edwards

Date: 9/8/2021

Impoundment Name: Ash Por			1		Time: 9:30 44	1	•		
IEPA Number: W14380		-01	Inspector(s): Rick Kel						
Sky: Partly Temp.: 67.	8%	- p	recip. (last 48 hrs):	0.0"	Poo	l Elev.:	44	7.4	
YES" responses require description (size, depth, out the time of inspection. If "ACTION" selected is additional sheets as necessary. Circle General Control of the control	"INVES	TIGAT	E", please indicate da						
						ACTION			
ITEM	YES	NO		DESCRIPTIO	ON	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con	dition.	Good	/ Fair / Poor	Repairs:	Date:				
Cracking		V							
Settlement									
Erosion Rills								,	
Animal Burrows									
Misalignment									
Vegetation (greater than 12")									
UPSTREAM EMBANKMENT General Con	dition	Good	Y Fair / Poor	Repairs:	Date:				
Cracking									
Sloughing / Bulging		V							
Seepage									
Sink Holes									
Animal Burrows	1			7 - 2 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1					
Erosion Rills		V							
Slope Protection / Rip Rap		Y	/						
Vegetation (greater than 12")		V							
DOWNSTREAM EMBANKMENT General Con-	dition	8000	Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		1							
Seepage		V	2						
Sink Holes									
Sand Boils (indicate if flowing and color)		1							
Animal Burrows		1							
Erosion Rills									
Vegetation (greater than 12")									
SPILLWAY(S) General Con-	dition	Good	Hair / Poor	Repairs:	Date:				
Actively Flowing (provide depth)				"-1.5"					
Obstructions Present									
Seepage		V		11-11-11-11-11-1-1-1-1-1-1-1-1-1-1-1-1					
Sand Boils (indicate if flowing and color)									