CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Sand Boils (indicate if flowing and color)

Erosion Rills

Station:			_		Date: 11/10/2	2021		
Impoundment Name: Ash IEPA Number: W14380			_		Time: 11:00	4 M	-	
		5-01	•	Inspec	ctor(s): Rick K	elley		
Sky: Heavy Temp.:	53°F	- 1	Precip. (last 48 hrs):	0.0"	Poo	ol Elev.:	44	£7.
"YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "INVES	STIGA	FE", please indicate date	RIPTION" section. forwarded via em	"NO" response indicates n ail to Dam Safety Manager	o issues (were o	bserve
						ACTION		
ITEM	YES	NO		DESCRIPTIO	N	MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Settlement								
Erosion Rills								
Animal Burrows								
Misalignment		V		<u> </u>				\vdash
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition	Good	/ Fair / Poor	Repairs:	Date:			Mail.
Cracking		/	,					
Sloughing / Bulging		V						
Seepage		1						
Sink Holes						1		
Animal Burrows					· · · · · · · · · · · · · · · · · · ·	_		
Erosion Rills		1				1		
Slope Protection / Rip Rap								
Vegetation (greater than 12")						1		
DOWNSTREAM EMBANKMENT	General Condition	5000	/ Fair / Poor	Repairs:	Date:		3	
Cracking								
Sloughing / Bulging						+ - +		
Seepage						\vdash	-+	
Sink Holes		1				 	\dashv	
Sand Boils (indicate if flowing and color)		V				\vdash	-+	
Animal Burrows						\vdash	\dashv	
Erosion Rills				-		\vdash		
Vegetation (greater than 12")							$\overline{}$	
	Seneral Condition:	300d	Fair / Poor	Repairs:	Date:			
Actively Flowing (provide dept			2 1.5"		Dutc.			
Obstructions Present		V				 	-	
Seepage		V				 	\longrightarrow	